

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2021

Submitted Date:

04/09/2021

Document Number:

700702555

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 335176 _____ Ramsey, Scott _____ 2A Doc Num: _____
Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

1 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211269	WELL	PR	12/01/1996	GW	045-07028	FEDERAL RMV 63-19	PR
277916	WELL	PR	05/07/2006	GW	045-10820	FEDERAL RWF 443-19	PR
277917	WELL	PR	05/01/2020	GW	045-10819	FEDERAL RWF 343-19	PR

General Comment:[COGCC Inspection Report Summary](#)

On Thursday 4/8/2021 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RMV 63-19, at Location # 335176 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for tracking pad.

During this inspection the following possible compliance issues were observed:

1. Location show signs of lack of stabilization/compaction

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 3		
Comment:	Braden heads have a port for manual gauge monitoring		
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
-----------------	--	--	--

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 211269 Type: WELL API Number: 045-07028 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID: 277916 Type: WELL API Number: 045-10820 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID: 277917 Type: WELL API Number: 045-10819 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					
		Berms				
Berms						
		Ditches				
Ditches						

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for tracking pad.
1. Location show signs of lack of stabilization/compaction

Corrective Action: Install or repair required BMPs

Date: 05/10/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402654547	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5399954
700702560	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5399949