

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402658128

Date Received:  
04/14/2021

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Michael Gardner</u>	<u>970-623-4875</u>	<u>mgardner@terraep.com</u>
		<u>COGCCInspectionReports@terraep.com</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 700702564  
Inspection Date: 04/12/2021 FIR Submit Date: 04/12/2021 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: GRIZZLY OPERATING LLC Company Number: 10531  
Address: 5847 SAN FELIPE #3000  
City: HOUSTON State: TX Zip: 77057

### LOCATION - Location ID: 335264

Location Name: GIBSON GULCH UNIT-66S91W Number: 30SENW County: \_\_\_\_\_  
Qtrqtr: SENW Sec: 30 Twp: 6S Range: 91W Meridian: 6  
Latitude: 39.499301 Longitude: -107.598441

### FACILITY - API Number: 05-045-00 Facility ID: 335264

Facility Name: GIBSON GULCH UNIT-66S91W Number: 30SENW  
Qtrqtr: SENW Sec: 30 Twp: 6S Range: 91W Meridian: 6  
Latitude: 39.499301 Longitude: -107.598441

### CORRECTIVE ACTIONS:

1 ☒ CA# 148329

Corrective Action: Install or repair required BMPs Date: 02/04/2021

Response: CA COMPLETED Date of Completion: 04/14/2021

Operator Comment: TEP disagrees with the determinaton that there is a lack of stabilization / compaction at this location. The photos show evidence of tire tracks only ... not excessive rutting. The presence of tire tracks does not mean that the site is unstable and is out of compliance. TEP will gladly meet with the inspector on-site to discuss if so desired.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

--

**OPERATOR COMMENT AND SUBMITTAL**

Comment: TEP disagrees with the claim that the site lacks compaction and is not stabilized. The shallow tire tracks do not indicate the site is unstable and out of compliance. TEP will gladly meet with inspector on-site to discuss if desired.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental

Date: 4/14/2021 11:53:03 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
-------------------------------	---------------------------

402658128	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files