

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/19/2021

Submitted Date:

04/20/2021

Document Number:

697601273

FIELD INSPECTION FORM

Loc ID 476325 Inspector Name: GINTAUTAS, PETER On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Knop, Max	303-825-4822	MKnop@kpk.com	
Inspections, KPK		cogcc@kpk.com	All KPK Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478861	SPILL OR RELEASE	AC	12/18/2020		-	Premium Turkey Farm PW Vault	EI

General Comment:

[environmental inspection of spill 478861 and associated site investigation and remediation project 16538 past corrective actions still to be completed unless acknowledged as completed with FIRRs.](#)

Inspected Facilities

Facility ID: 478861 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER Estimated Spill Volume: 250

Comment: no investigation of impacts and no effort to determine horizontal and vertical extent of impacts has been initiated at the time of this inspection as seen in attached photo. Rule 912.a (1) requires that Operators will control and contain the Spill or Release to protect and minimize adverse impacts to public health, safety, welfare, the environment, and wildlife resources. rule 912.b(2) requires that Operators will investigate, clean up, and document impacts resulting from Spills and Releases as soon as the impacts are discovered.

Corrective Action: Comply with 912.a(1) and 912.b(2) as described above and rule 913.b(2) which requires that the full horizontal and vertical extent be determined by conducting sampling and analysis of soils and groundwater (if present) and groundwater may be shallow at the site. Date: 05/20/2021

Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: remediation project 16538 remains open
no updated implementation schedule was submitted with the most recent form 27 update as required by rule .

Corrective Action: Provide an updated implementation plan in a supplemental form 27 as required by rules 913.d which must include planned dates to complete investigation and remediation. Date: 05/20/2021

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697601274	PW vault and impacts still in place	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408730