

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/26/2021

Submitted Date:

04/26/2021

Document Number:

697601298

FIELD INSPECTION FORMLoc ID 476325 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Knop, Max	303-825-4822	MKnop@kpk.com	
Inspections, KPK		cogcc@kpk.com	All KPK Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478861	SPILL OR RELEASE	AC	12/18/2020		-	Premium Turkey Farm PW Vault	EI

General Comment:

environmental inspection of spill 478861 and associated site investigation and remediation project 16538
past corrective actions still to be completed unless acknowledged as completed with FIRRs.

No investigation of impacts has been performed at this site at time of inspection.

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 250

Comment: no investigation of impacts and no effort to determine horizontal and vertical extent of impacts has been initiated at the time of this inspection as seen in attached photo. Rule 912.a(1) requires that Operators will control and contain the Spill or Release to protect and minimize adverse impacts to public health, safety, welfare, the environment, and wildlife resources. rule 912.b(2) requires that Operators will investigate, clean up, and document impacts resulting from Spills and Releases as soon as the impacts are discovered.

Corrective Action: Comply with 912.a(1) and 912.b(2) as described above and rule 913.b(2) which requires that the full horizontal and vertical extent be determined by conducting sampling and analysis of soils and groundwater (if present) and groundwater may be shallow at the site.

Date: 05/20/2021

Reportable: YES

GPS: Lat

Long

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

Field Parameters:

Sample Location:

Comment:

Spill/Remediation:

Comment: remediation project 16538 remains open
no updated implementation schedule was submitted with the most recent form 27 update as required by rule .

Corrective Action: Provide an updated implementation plan in a supplemental form 27 as required by rule 913.d which must include planned dates to complete investigation and remediation.

Date: 05/20/2021

Emission Control Burner (ECB):

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697601299	concrete vault still in place	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5413135
697601300	PW vault and sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5413136