

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/23/2021

Submitted Date:

04/26/2021

Document Number:

696202604**FIELD INSPECTION FORM**Loc ID 314804 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 100 CHEVRON ROADCity: RANGELY State: CO Zip: 81648**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Olson, Andrew		andrewolson@chevron.com	Principal Agent
Patterson, Chris		spwu@chevron.com	All Inspections per Olson

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229626	WELL	TA	06/18/1998	ERIW	103-07283	CARNEY C T 24X35	RI
314804	LOCATION	AC			-	CARNEY C T-62N102W 35NWNE	RI

General Comment:

On 4/23/2021, Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at Chevron USA Inc's Carney C T 24X35 location in Rio Blanco County, Colorado.

This inspection is a followup to #696202348 to document compliance with the following corrective actions:

606: Good Housekeeping

1002.f: Stormwater

Refer to the "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type

Comment:

Inspection #696202348 observed various cable/wood debris on the western slopes of the Location.

It was observed in this inspection that the debris has been removed. This CA has been addressed.

Corrective Action: Date: Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment: Corrective Action: Date: **Flaring:**

Type

Comment: Corrective Action: Date:

Inspected Facilities									
Facility ID:	229626	Type:	WELL	API Number:	103-07283	Status:	TA	Insp. Status:	RI
Facility ID:	314804	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Inspection #696202348 observed erosion degradation on the western slopes of the Location. Inspection required Operator to comply with Rule 1002.f.(2)C. It was observed in this inspection that the erosion has been repaired, and erosion logs installed. This CA has been addressed.

NEW Corrective action:

It was observed in this inspection that control measures to stabilize the production area, and to prevent off-site sediment transport during wet conditions are missing or insufficient.

Corrective Action: Comply with Rule 1002.f.(2)C and install required stormwater and erosion control BMPs; ensure control measures are adequate for the site's conditions, installed in accordance with good engineering practices, and are maintained in a proper functioning condition.

Date: 04/30/2021

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402670676	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5412736
696202605	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5412732