

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/06/2021

Submitted Date:

05/06/2021

Document Number:

699103584

FIELD INSPECTION FORM
 Loc ID 410006 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Frishmuth, Rusty		rfrishmuth@hpres.com	All Inspections
Reese, Jason		jreese@hpres.com	All Inspections
Paben, Brett		bpaben@hpres.com	All Inspections
Neighbors, Cory		cneighbors@hpres.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
132	WELL	PR	01/01/2019	GW	123-25423	PETERSON 30-31	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:		Date:	

Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil next to the well needs to be removed. See attached photo.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."		Date: 05/17/2021
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment next to the well, needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606		Date: 05/17/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	#		
Comment:	Master valves appear to be leaking, fix or replace. See attached photo.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 05/17/2021
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		

Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Type			
Comment:			
Corrective Action:		Date:	

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 132 Type: WELL API Number: 123-25423 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 09/02/2020Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary

On Thursday 5/6/21 at approximately 1155hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Peterson 30-31 of Highpoint Resources, at Location ID # 410006 in Weld County, Colorado.

During this inspection the following possible compliance issues were observed:

Unused equipment needs to be removed for good housekeeping. Comply with Rule 606.

With a corrective action date of 5/17/21

Stain soil next to the well needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 5/17/21

Master valves appear to be leaking, fix or replace. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a corrective action date of 5/17/21

See attached photos.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

burnsa

05/06/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103585	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5422650