

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2021

Submitted Date:

05/07/2021

Document Number:

696202652

FIELD INSPECTION FORM

Loc ID 418697	Inspector Name: Trujillo, Aaron	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 4 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 77330 Name of Operator: SG INTERESTS I LTD Address: 100 WAUGH DR SUITE 400 City: HOUSTON State: TX Zip: 77007				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		inspection@sginterests.com	All Inspections
,		dnr_cogccenforcement@state.co.us	
Arthur, Denise		denise.arthur@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418693	WELL	PA	07/11/2019	GW	051-06098	VOLK 12-89-21 #1	RI
418697	LOCATION	CL			-	VOLK 12-89-21 #1	RI

General Comment:

On 3/31/2021, Reclamation Specialist Trujillo conducted a final reclamation and stormwater inspection at SG Interests' Volk 12-89-21 #1 location in Gunnison County, Colorado.

This inspection is a followup to inspection:

#696201320 dated 5/26/2020,

#696201669 dated 8/31/2020,

#696202023 dated 11/19/2020

and #696202524 dated 3/31/2021 to document compliance with the following corrective actions:

1002.f.(2)C: Install or repair required BMPs in accordance with good engineering practices and conduct revegetation/reseeding activities by 6/11/2020.

It was observed in this inspection that the Location remains out of compliance with COGCC Rules and corrective actions. However, Operator was onsite at time of inspection, and work to address stormwater and reclamation compliance issues was observed to be in process.

Refer to the "Stormwater" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities									
Facility ID:	418693	Type:	WELL	API Number:	051-06098	Status:	PA	Insp. Status:	RI
Facility ID:	418697	Type:	LOCATION	API Number:	-	Status:	CL	Insp. Status:	RI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Previous inspection observed that stormwater and erosion control measures on the Location were insufficient, or missing in accordance with Rule 1002.f.(2)C. Inspections required Operator to comply with Rule 1002.f.(2)C by 6/11/2020.

It was observed in this inspection that though the Location remains out of compliance with COGCC 1002.f. Stormwater Rules, Operator was onsite at time of inspection, and work to address the stormwater and reclamation compliance issues was observed to be in process.

Original CA and date will remain applicable until work has been completed to address the CA in its entirety, and a followup inspection is conducted to determine compliance with stormwater Rules.

Corrective Action: Install or repair required BMPs in accordance with good engineering practices per Rule 1002.f.(2)C. Conduct revegetation/reseeding activities on the slopes and install erosion controls to stabilize the seeded soil.

Date: 06/11/2020

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Operator is requested to submit a FIRR once work to address the stormwater and reclamation concerns have been completed.	trujilloam	05/07/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696202653	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5423594