

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402665813

Date Received:

04/21/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Jones, Tammy

tajones@hilcorp.com

Shorty, Priscilla

pshorty@hilcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693902544

Inspection Date: 11/20/2020

FIR Submit Date: 11/24/2020

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326687

Location Name: PENROSE-N32N6W Number: 8SWSW County: LA PLATA

Qtrqr: SWS Sec: 8 Twp: 32N Range: 6W Meridian: N
W

Latitude: 37.027520 Longitude: -107.529450

FACILITY - API Number: 05-067- -00 Facility ID: 262950

Facility Name: PENROSE Number: 1R

Qtrqr: SWS Sec: 8 Twp: 32N Range: 6W Meridian: N
W

Latitude: 37.027520 Longitude: -107.529450

CORRECTIVE ACTIONS:

1 ☒ CA# 144654

Corrective Action: Remove and properly dispose of weed debris.

Date: 12/31/2020

Response: CA COMPLETED

Date of Completion: 12/21/2020

Operator
Comment:

The weeds have been removed and properly disposed. See attached photo.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2  CA# 144655

Corrective Action: Repair/replace BMPs within the project area.

Date: 12/31/2020

Response: CA COMPLETED

Date of Completion: 04/20/2021

Operator
Comment: Hilcorp Pipeline has verified that the BMPs/straw wattles are on Red Cedar pipeline right of way. 4/21/2021 - See attached photos showing resolution

COGCC Decision: **Not Approved**

COGCC
Representative: Review of aerial imagery and well history demonstrates that the disturbance east of the production area is part of the original well pad disturbance. This area needs to be stabilized with desirable perennial vegetation and BMPs installed and maintained.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 4/21/2021 6:54:22 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402665813	FIR RESOLUTION SUBMITTED
402665821	Weeds Removed Photos
402665822	BMP Photos

Total Attach: 3 Files