

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402666927

Date Received:

04/21/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Ray, Mandy</u>	<u>(505) 599-4083</u>	<u>mray@hilcorp.com</u>
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693902552

Inspection Date: 12/01/2020

FIR Submit Date: 12/04/2020

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326297

Location Name: HUBER-LEWIS-N35N8W Number: 33SWSE County: LA PLATA
Qtrqtr: SWSE Sec: 33 Twp: 35N Range: 8W Meridian: N
Latitude: 37.253760 Longitude: -107.747900

FACILITY - API Number: 05-067- -00 Facility ID: 216188

Facility Name: HUBER-LEWIS Number: 2-33
Qtrqtr: SWSE Sec: 33 Twp: 35N Range: 8W Meridian: N
Latitude: 37.253760 Longitude: -107.747900

CORRECTIVE ACTIONS:

1 ☒ CA# 144885

Corrective Action: -Operator needs to assess the cause of vegetation die-off (ie bareground herbicide runoff, etc.) within the eastern project area and take actions to prevent further degradation. Submit plan via Form 4 that describes measures taken to prevent further vegetation loss including a description of any stormwater BMPs, changes in herbicide schedule or type, soil sampling, seeding, and timeline, by 12/30/2020.

Date: 12/30/2020

Response: CA COMPLETED

Date of Completion: 04/20/2021

We have submitted a Form 4 Doc No: 402558033, with the following information listed out: Hilcorp Energy has assessed the cause of vegetation die-off and believe it was a result of a late season herbicide treatment in the fall

Operator Comment: of 2018 followed by an extremely wet winter. Snow was bladed off the location and piled near the eastern edge of location were during the spring runoff it melted and flowed off of location with the herbicide causing the vegetation die-off.

Corrective Action:

1. Herbicide treatments will only be conducted during late spring early summer to prevent further vegetation loss from storm water runoff.
2. Storm water controls will be establish along the eastern edge of location. A diversion will be installed by May 31st 2021 that will run north to south on the eastern edge of location that will spill the storm water out on a flat area just north of the north rig anchor to prevent further head cutting along the eastern edge of location.
3. Hilcorp will not conduct soil samples at this time since we know the origin of the vegetation die-off.
4. Barren flow path areas along the eastern edge of location will be treated with Humate soil conditioner and seeded by May 31st 2021.

See attached photos showing resolution.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 4/21/2021 2:47:01 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402666927	FIR RESOLUTION SUBMITTED
402666943	Huber Lewis 2-33 Resolved Photos

Total Attach: 2 Files