

GOLDEN EAGLE 31-04 API# 05-071-08352 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: MAY 14, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103420



PHOTO 1: THE LEAKS ON THE COMPRESSOR WERE REPAIRED. ALL FITTINGS ARE SECURLY FASTENED.  
THE FLUID ACCUMULATION WAS REMOVED FROM THE CONTAINMENT



GOLDEN EAGLE 31-04 API# 05-071-08352 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: MAY 14, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103420



PHOTO 2: THE LEAKING MUFFLER ON THE ENGINE SKID WAS REPAIRED AND THE IMPACTED SOIL ON THE GROUND WAS REMOVED.



GOLDEN EAGLE 31-04 API# 05-071-08352 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: MAY 14, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103420



PHOTO 3: THE LEAKING MUFFLER ON THE ENGINE SKID WAS REPAIRED AND ALL FITTINGS WERE SECURLY FASTENED.



GOLDEN EAGLE 31-04 API# 05-071-08352 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10672 - DATE: MAY 14, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695103420



PHOTO 4: THE SCRUBBER LIQUID WAS REMOVED FROM THE PRODUCED WATER TANK AND DISPOSED OF PER OGRIS'S WASTE MANAGEMENT PLAN AND THE COGCC RULES AND REGULATIONS.