

Inspection Photos

5/14/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 452055

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 452055



Photo 1: Photo taken from the north end of the Location, facing east. Photos 1-4 provide an overview of the production area from east, south, southwest to west.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 452055



Photo 2: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 452055



Photo 3: See comments under photo 1.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 452055



Photo 4: See comments under photo 1.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 452055




Photo 5: Photo taken from the interim areas on the south end of the Location, facing south. Interim reclamation in process. Photo also shows rill erosion becoming evident on the south end of the Location. BMPs to manage stormwater runoff from the Location, and to protect/stabilize slopes missing or insufficient.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 452055



Photo 6: Photo taken from the interim areas on the southwest end of the Location, facing west. Interim reclamation in process.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 452055



Photo 7: Photo taken from the interim areas on the southwest end of the Location, facing northwest. Interim reclamation in process.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 452055



Photo 8: Photo taken from the cut slopes on the east end of the Location. Operator appears to have previously installed a hydromulch to the cut slopes; BMP is no longer in proper functioning condition; control measures to protect/stabilize cut slopes missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 452055



Photo 9: See comments under photo 8

