

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/19/2021

Submitted Date:

05/19/2021

Document Number:

696303264

FIELD INSPECTION FORM

Loc ID 319114 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 70385
Name of Operator: SMITH ENERGY CORP
Address: 12706 SHILOH RD
City: GREELEY State: CO Zip: 80631

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 12 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Smith, Glenn	(970) 330-7034	gsmithten@what-wire.com	
Smith, Chris	(970) 330-7034	smithenergy@live.com	
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242917	WELL	SI	06/01/2018	OW	123-10708	FARNIK-WELD COUNTY 2X	SI

General Comment:

[Follow-Up Inspection to FIR 696300717 dated 10.18.2019](#)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign is not legible/fading. See photos		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	11/18/2019
Type	BATTERY		
Comment:	Tank Battery sign is not legible/faded. See photos		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	11/18/2019
Type	TANK LABELS/PLACARDS		
Comment:	50 BBIs Skim Tank - Capacity Missing. See photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/18/2021

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds at Tank Battery, Heater Treater and pit. See photos		
Corrective Action:	Comply with Rule 606	Date:	11/18/2019

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Adequate		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 0		
Comment:	Bradenhead appears to be NOT plumbed to surface		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)		Date: 05/31/2021

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		40.536370,-103.944180
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities

Facility ID: 242917 Type: WELL API Number: 123-10708 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI - Since 06.01.2018. NO MIT on Record.
Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42.
Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 06/18/2021

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding		Seeding				

Comment: Pasture

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: _____ Pit ID: _____ Lat: 40.535990 Long: -103.944160

Reference Point: SE Other: _____ Length: 15 Width: 10

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment: Barbed Wire

Corrective Action

Date:

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date:

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 05/18/2021 at approximately 13:03, I, Inspector Erica Petrie, conducted a Field Follow-Up Inspection at Smith Energy Corporation, Farnik Weld County 2X at Location #319114 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed: Well and Tank Battery Shut-IN</p> <p>Tank Battery and Wellhead signs have faded and are no longer legible, see photos. Comply with 605 Series Rules for Signage. SAME Corrective Action Date 11/18/2019 is STILL applicable. As issues NOT ADDRESSED.</p> <p>Weeds at Tank Battery, Heater Treater and Pit. See photos. Comply with Rule 606. SAME Corrective Action Date 11/18/2019 is STILL applicable. As issues NOT ADDRESSED.</p> <p>Well is Shut-In Since 06.01.2018. NO MIT on Record. Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention. Corrective Action Date 06.18.2021 or as Stated by COGCC Engineering Department.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing Educational Inspections</p>	petrie	05/19/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696303265	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5434704