

Colorado Oil and Gas Conservation Commission

Gunnison Energy- Trail Gulch #453805 Issue Report



Created on May 24, 2021

Captured: May 21, 2021



Issue Type	Count
Other	5

No.	Summary	Type	Created	Status
5	Northwestern unused disturbed areas requiring 1003 reclamation.	Other	May 24, 2021, 12:31pm	Open
4	Inspection #696202645 required 1003.b reclamation for southern disturbed areas of the Location not needed for production. A portion of these areas have since been staked for the construction of a sediment trap/pond, as part of the construction of the Trail Gulch Unit 1090 /30. Corrective action will remain applicable for unused areas on the south end of the Location not part of the sediment trap, unless BMP is not constructed, at which point the all unused, disturbed areas remain subject to Rule 1003.b.	Other	May 24, 2021, 12:30pm	Open
3	Spill, requires cleaning	Other	May 24, 2021, 11:17am	Open
2	Canada thistle rosettes observed within sediment trap.	Other	May 24, 2021, 11:16am	Open
1	Construction of the silt fence appears to have compromised the integrity of the containment BMP at the tank.	Other	May 24, 2021, 11:16am	Open

1 - Other **OPEN**

May 21, 2021 at 10:52am



Type
Other

Lat/Long
39.15624, -107.47750

Summary
Construction of the silt fence appears to have compromised the integrity of the containment BMP at the tank.

Created
May 24, 2021 at 11:16am by Aaron Trujillo

2 - Other **OPEN**

May 21, 2021 at 10:52am



Type
Other

Lat/Long
39.15600, -107.47762

Summary
Canada thistle rosettes observed within sediment trap.

Created
May 24, 2021 at 11:16am by Aaron Trujillo

3 - Other **OPEN**

May 21, 2021 at 10:52am



Type
Other

Summary
Spill, requires cleaning

Lat/Long
39.15646, -107.47804

Created
May 24, 2021 at 11:17am by Aaron Trujillo

4 - Other OPEN

May 21, 2021 at 10:52am

**Type**

Other

Lat/Long

39.15622, -107.47808

Summary

Inspection #696202645 required 1003.b reclamation for southern disturbed areas of the Location not needed for production. A portion of these areas have since been staked for the construction of a sediment trap/pond, as part of the construction of the Trail Gulch Unit 1090 /30. Corrective action will remain applicable for unused areas on the south end of the Location not part of the sediment trap, unless BMP is not constructed, at which point the all unused, disturbed areas remain subject to Rule 1003.b.

Created

May 24, 2021 at 12:30pm by Aaron Trujillo

5 - Other **OPEN**

May 21, 2021 at 10:52am



Type
Other

Lat/Long
39.15645, -107.47833

Summary
Northwestern unused disturbed areas requiring 1003 reclamation.

Created
May 24, 2021 at 12:31pm by Aaron Trujillo

Inspection Photos

5/21/2021

Operator: GUNNISON ENERGY LLC # 10515

Location ID: 324464

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 1: Photo shows stained soils in front of diesel tank.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 2: Photo show repair equipment and clean-up of stained soils around equipment was in process at time of inspection

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 3: Photo show repair equipment and clean-up of stained soils around equipment was in process at time of inspection

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 4: Photo taken from the 300 bbl produced water tank on the Location. Photo shows that the integrity of the containment berm BMP has been compromised during the construction of a silt fence.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 5: Photo taken from the 300 bbl produced water tank on the Location. Photo shows that the integrity of the containment berm BMP has been compromised during the construction of a silt fence.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 6: Photos 6-11 provide examples of various trash, debris and unused equipment remaining on the Location.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 7: See comments under photo 6.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 8: See comments under photo 6.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 9: See comments under photo 6.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 10: See comments under photo 6.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 11: See comments under photo 6..

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324464



Photo 12: Photo taken from the fill slopes on the southeast end of the Location. Photo shows BMPs to protect/stabilize the fill slopes of the Location remain missing or insufficient.

Inspection Photos

Operator Name: GUNNISON ENERGY LLC # 10515

Location ID: 324464



20210521

Photo 13: Photo taken from the interim areas on the west end of the Location, facing north. Desirable perennial vegetative establishment is sparse; interim areas largely bare. Vegetation observed on interim areas predominantly undesirable weedy plant species.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources