

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/31/2021

Submitted Date:

05/31/2021

Document Number:

701600076

FIELD INSPECTION FORM

Loc ID: 312327 Inspector Name: SCHURE, KYM On-Site Inspection: 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 11001
Name of Operator: BROWN OIL & GAS LLC
Address: 10481 COUNTY ROAD 20.5
City: STERLING State: CO Zip: 80751

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Schure, Kym		kym.schure@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284011	WELL	SI	10/01/2018	OW	075-09351	CEDAR CREEK RANCH 1-Y	SI

General Comment:

Commencing P&A - Wet conditions causing delay in process. RIG ON SITE -

Inspected Facilities

Facility ID: 284011 Type: WELL API Number: 075-09351 Status: SI Insp. Status: SI

Cement

Cement Contractor

Contractor Name: Yetter Well Service

Contractor Phone: 970-522-2885

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment:

Corrective Action:

Date: _____

Idle Well

Purpose: Shut In Temporarily Abandoned

Reminder: _____

Comment:

Corrective Action:

Date: _____

COGCC Comments

Comment	User	Date
Commencing P&A - Muddy surface conditions causing delay	schureky	05/31/2021