



Talon 34-25



Installed appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)