

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/15/2021

Submitted Date:

06/17/2021

Document Number:

696202822

FIELD INSPECTION FORM

Loc ID 324464 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10515
Name of Operator: GUNNISON ENERGY LLC
Address: 1801 BROADWAY #1150
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		tyson.johnston@oxbow.com	
		heather.lang@oxbow.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
324464	LOCATION	AC			-	FEDERAL-610S90W 30SWSE	RI

General Comment:

On 6/15/2021, Reclamation Specialist Trujillo conducted an interim reclamation and storm water inspection at Gunnison Energy's Federal 30-4 location in Gunnison County, Colorado.

This inspection is a followup to #696202645 and #696202706 to document compliance with the following corrective actions
 606: Good Housekeeping (5/22/2021)
 608.e: Mechanical Conditions (5/22/2021)
 912: Spills and Releases (5/22/2021)
 1003.b: Reclamation of areas no longer needed for production (6/7/2021)
 1003.f: Noxious weed management (6/24/2021)

It was observed in this inspection that the Location remains out of compliance with COGCC Rules and corrective actions.

Refer to the "Location" and "Reclamation" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	<p>Inspection #696202645 and 696202706 observed various trash, debris and unused equipment stored throughout the Location.</p> <p>It was observed in this inspection that the various trash, debris and unused equipment remains on the Location; original corrective action and date remains applicable.</p>		
Corrective Action:	Comply with Rule 606	Date:	05/22/2021

Type	WEEDS		
Comment:	<p>Previous inspection observed noxious weeds (Canada thistle) on the Location, and required Operator to comply with Rule 1003.f.</p> <p>It was observed in this inspection that other noxious weed species (Hoary cress, Musk thistle, Bindweed) have established on the Location. Inspector observed signs indicating herbicide application was performed, though it is unclear if the recent weed management was adequate.</p> <p>Continue noxious weed monitoring/management. A followup inspection will be performed to determine compliance with Rule 1003.f</p>		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			
Comment:	<p>Previous inspections observed equipment on the west end of the Location was leaking, resulting in a spill/stained soils in the immediate are of the equipment. Previous inspection observed work to address the mechanical issues was in process.</p> <p>It was observed in this inspection that the stained soils have been cleaned, however mechanical issues appear to remain, and new fluids have been observed at the base of the equipment. Work to control/contain releases, and to ensure good mechanical condition of the equipment appears to be insufficient.</p> <p>Corrective actions will remain applicable.</p>				
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.			Date:	05/22/2021

In Containment: No

Comment:

Previous inspection observed stained soils in front of a temporary diesel tank. Operator was required to comply with Rule 912.a.

It was observed in this inspection that the stained soils have been cleaned/removed. This corrective action has been addressed.

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

Comment:			
Corrective Action:			Date:

Paint

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				

Comment:	<p>Previous inspection observed that the integrity of the containment BMP at the tanks was inadequate.</p> <p>It was observed in this inspection that the secondary containment BMPs appears to remain inadequate to contain 150% of the volume of the tank. It was also observed that secondary containment for the other two tanks on the Location also appears inadequate.</p>		
Corrective Action:	<p>Repair or install berms or other secondary containment devices per Rule 603.o. Ensure secondary containment is adequate to contain 150% of the volume of the tank(s).</p> <p>If Operator believes containment is adequate in accordance with Rule 603.o, the Operator will be required to submit calculations and figures (attached to a FIRR) including the diameter of the tanks, showing secondary containment complies with Rules.</p>		Date: <u>06/24/2021</u>

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 324464 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____ Fail _____

Comment [Equipment/vehicles observed placed on areas subject to interim reclamation.](#)

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? Fail Production areas stabilized? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? F

Comment

Corrective Action Date 06/07/2021

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

COGCC Comments

Comment	User	Date
<p>INTERIM RECLAMATION COMMENTS</p> <p>Previous inspections observed areas on the northwest, and southern end of the Location require reclamation in accordance with Rule 1003.b by 6/7/2021.</p> <p>Inspection #696202645 also observed that a sediment trap/pond was planned for construction on the southern areas of the Location as part of the construction of the Trail Gulch Unit 1090 /30.</p> <p>COGCC notified Operator within previous inspections, and within a phone meeting with the Principal Agent, that the corrective action to conduct interim reclamation will remain applicable for the identified areas, and for unused areas on the south end of the Location not part of the sediment trap, unless BMP is not constructed, at which point all unused, disturbed areas will remain subject to Rule 1003.b.</p> <p>It was observed in this inspection that interim reclamation of areas not needed for production has not been performed in accordance with 1003 rules; equipment observed stored on the northwestern areas. Trailer observed stored on the southern areas, sediment trap/pond has not been constructed.</p> <p>This corrective action has not been addressed and remains applicable.</p>	trujilloam	06/17/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696202823	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5458255