

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402725168

Date Received:

06/21/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Byers, Jim

jbyers@blm.gov

\_\_\_\_\_"

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202812

Inspection Date: 06/10/2021

FIR Submit Date: 06/14/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335171

Location Name: FEDERAL-66S95W Number: 31NENW County: \_\_\_\_\_

Qtrqtr: NENW Sec: 31 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.486621 Longitude: -108.042692

FACILITY - API Number: 05-045- -00 Facility ID: 335171

Facility Name: FEDERAL-66S95W Number: 31NENW

Qtrqtr: NENW Sec: 31 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.486621 Longitude: -108.042692

CORRECTIVE ACTIONS:

1 CA# 151879

Corrective Action: Comply with Rule 1002.f.(2)C: Install or repair required Stormwater and Erosion control BMPs. Ensure control measures on the Location are adequate for the site's conditions, installed in accordance with good engineering practices, and maintained in proper functioning condition.

Date: 02/07/2021

Response: CA COMPLETED

Date of Completion: 06/16/2021

Operator Comment: Cut slope has been sprayed / covered with two coats of a durable hydromulch. TEP personnel will continue to monitor the stability of this cut slope. Additional mulch may be applied as site conditions warrant. Corrective action is complete.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

--

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Corrective action is complete. A dual coat of durable hydromulch has been applied to the cut slope. TEP will continue to monitor performance of the hydro mulch, and re-apply as needed. This CA for this site is ready for reinspection.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental

Date: 6/21/2021 5:12:30 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
-------------------------------	---------------------------

--	--

Total Attach: 0 Files