

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402709587

Date Received:  
06/07/2021

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Christina Pierce

970-263-3626

cpierce@Laramie-Energy.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 696202101

Inspection Date: 12/08/2020

FIR Submit Date: 12/09/2020

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1401 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 324315

Location Name: CC Number: 0610-22-43 County: \_\_\_\_\_  
Pad

Qtrqtr: SENW Sec: 10 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.539277 Longitude: -108.207040

### FACILITY - API Number: 05-045- -00 Facility ID: 324315

Facility Name: CC Number: 0610-22-43  
Pad

Qtrqtr: SENW Sec: 10 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.539277 Longitude: -108.207040

### CORRECTIVE ACTIONS:

2 ☒ CA# 144996

Corrective Action: Comply with Rule 1002.f.(2) and install BMPs in accordance with good engineering practices. Temporary controls will be required by 1/9/2021 until interim reclamation of the Location is conducted, at which point long-term controls will need to be implemented.

Date: 01/09/2021

Response: CA COMPLETED

Date of Completion: 06/04/2021

issue addressed see attached report

Operator  
Comment:

COGCC Decision: **Not Approved**

COGCC  
Representative:

Inspection documented that BMPs to stabilize and protect the cut/fill slopes of the Location, and to prevent off-site sediment transport are missing or insufficient.

Documentation attached show BMPs to manage runoff have been implemented; a followup inspection will need to be conducted to determine if BMPs are adequate for the site's conditions, and have been installed in accordance with good engineering practices. Operator has not provided any documentation showing that control measures to stabilize and protect the slopes of the Location have been implemented.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Christina Pierce

Signed:

Title: Engineering Tech

Date: 6/7/2021 9:45:00 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402709587	FIR RESOLUTION SUBMITTED
402709592	corrective action

Total Attach: 2 Files