

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402718208

Date Received:
06/16/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>.TEP</u>		<u>COGCCInspectionReports@terraep.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202691
Inspection Date: 05/14/2021 FIR Submit Date: 05/19/2021 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 452055

Location Name: CHEVRON Number: TR 23-22-597 County: _____
Qtrqtr: NESW Sec: 22 Twp: 5S Range: 97W Meridian: 6
Latitude: 39.595644 Longitude: -108.265181

FACILITY - API Number: 05-045-00 Facility ID: 452055

Facility Name: CHEVRON Number: TR 23-22-597
Qtrqtr: NESW Sec: 22 Twp: 5S Range: 97W Meridian: 6
Latitude: 39.595644 Longitude: -108.265181

CORRECTIVE ACTIONS:

1 CA# 151145

Corrective Action: Comply with Rule 1002.f and install required stormwater and erosion control BMPs; ensure control measures are adequate for the site's conditions, are installed in accordance with good engineering practices, and maintained in proper functioning condition.

Date: 05/21/2021

Response: CA COMPLETED Date of Completion: 06/11/2021

Site is in compliance with Rule 1002.f. Required stormwater and erosion control BMPs are in place. Control measures are adequate for the site's conditions and are installed in accordance with good engineering practices, and are maintained in proper functioning position.

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Operator has provided no documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: CAs have been completed. Site is ready for re-inspection.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 6/16/2021 3:27:22 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402718208	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files