

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402720079

Date Received:
06/16/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

| | | |
|-------------------------|---------------------|-----------------------------------|
| Contact Name | Phone | Email |
| <u>Christina Pierce</u> | <u>970-263-3626</u> | <u>cpierce@Laramie-Energy.com</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202676

Inspection Date: 05/14/2021

FIR Submit Date: 05/18/2021

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1401 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 452807

Location Name: CC Number: 0697-03-07 County: _____
Pad

Qtrqtr: Lot 11 Sec: 3 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.558439 Longitude: -108.205081

FACILITY - API Number: 05-045- -00 Facility ID: 452807

Facility Name: CC Number: 0697-03-07
Pad

Qtrqtr: Lot 11 Sec: 3 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.558439 Longitude: -108.205081

CORRECTIVE ACTIONS:

2 CA# 151140

Corrective Action: Comply with Rule 1002.f.(2) and install BMPs in accordance with good engineering practices. Temporary controls will be required by 1/10/2021 until interim reclamation of the Location is conducted, at which point long-term controls will need to be implemented.

Date: 01/10/2021

Response: CA COMPLETED Date of Completion: 06/15/2021

hydromulch application along the access road see attached report

Operator
Comment:

COGCC Decision: **Not Approved**

COGCC
Representative:

Inspection #696202676 documented that BMPs to protect, stabilize and prevent off-site sediment transport from the cut and fill slopes of the Location, and access road are missing or insufficient.

Documentation attached to resolution shows additional work and stabilization controls have been implemented along the access road, however, Operator has not provided any documentation showing that control measures to stabilize and protect the remaining slopes of the Location have been implemented per the corrective action.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Christina Pierce

Signed: _____

Title: Engineering Tech

Date: 6/16/2021 8:32:05 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------------|
| 402720079 | FIR RESOLUTION SUBMITTED |
| 402720081 | corrective action |

Total Attach: 2 Files