

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402726587

Date Received:
06/22/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202702

Inspection Date: 05/14/2021

FIR Submit Date: 05/19/2021

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335961

Location Name: CHEVRON Number: TR 11-1-698 County: _____

Qtrqr: NWS Sec: 1 Twp: 6S Range: 98W Meridian: 6
W

Latitude: 39.561495 Longitude: -108.285197

FACILITY - API Number: 05-045- -00 Facility ID: 335961

Facility Name: CHEVRON Number: TR 11-1-698

Qtrqr: NWS Sec: 1 Twp: 6S Range: 98W Meridian: 6
W

Latitude: 39.561495 Longitude: -108.285197

CORRECTIVE ACTIONS:

1 ☒ CA# 151148

Corrective Action: Comply with Rule 406.e.(4) and plug and reclaim conductors. Comply with Rule 1003 and perform interim reclamation of the Location. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed. A CA date of 5/10/2021 is being provided as this was when interim reclamation was required by, per Sundry #402135498 conditions.

Date: 05/10/2021

Response: CA COMPLETED

Date of Completion: 06/08/2021

All conductors have been physically closed per Rule 406.e.(4) Additionally, Form 4s have been submitted to close the conductors and abandon the expired drilling permits for the Chevron TR 11-1-698 well pad. Interim

Operator
Comment: reclamation of the location has been completed.

COGCC Decision: Approved pending re-inspection

COGCC
Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Operator has provided no documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: This Corrective Action has been completed. Per the requirements of Rule 406.e.(4), all conductors have been closed and Form 4s have been submitted to abandon the expired drilling permits for this location. Interim reclamation of the location has been completed. The site is ready for reinspection.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental

Date: 6/22/2021 3:31:45 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402726587	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files