



Whiting Oil & Gas Corporation

HILL 6-6 CORRECTIVE ACTION INSPECTION PHOTOS

Location ID: 315155

Sec 6 T1N R101W

6/24/2021



Weeds around the location removed, location berms repaired, remove chemical tank with damaged secondary containment, and fix subsidence of ground at buried line marker.