

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/22/2021

Submitted Date:

06/24/2021

Document Number:

696202855

FIELD INSPECTION FORM

Loc ID 335815 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	All Inspections
Arthur, Denise		denise.arthur@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335815	LOCATION	AC			-	Cascade Creek 697-08-53	RI

General Comment:

On 6/23/2021, Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at Laramie Energy's Cascade Creek 697-08-53 location in Garfield County, Colorado.

This inspection is a followup to #696202120 to document compliance with the following corrective actions:

- Comply with Rule 606 by 12/25/2020
- Comply with Rule 1002.f by 1/11/2021
- Comply with 1003 Rules by 3/1/2016

This inspection is also a followup to Resolution Nos. 402560694 and 402706411 stating corrective actions for Rules 606 and 1002.f have been addressed.

It was observed in this inspection that the Location remains out of compliance with COGCC Rules and Corrective Actions.

Refer to the "Good Housekeeping", "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable; refer to inspection #701101419 for corrective actions regarding signage at tank battery.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	DEBRIS		
Comment:	<p>Inspection #696202120 observed various trash debris on the slopes of the Location. Inspection required Operator to comply with Rule 603.f (Now Rule 606) by 12/25/2020.</p> <p>It was observed in this inspection that the debris has been removed from the slopes of the Location.</p> <p>This corrective action has been addressed.</p>		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	335815	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI

--

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? Fail Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? Fail

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail

Production areas have been stabilized? _____ Segregated soils have been replaced? Fail

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Fail Recontoured Fail 80% Revegetation Fail

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Records show date of first production 4/4/2012; interim reclamation of the Location should have been conducted by 10/4/2012. Records show 03/01/2016 as the date Laramie took ownership of the Location.

Inspection #696202120 observed that interim reclamation of areas not needed for production on the Location has not been performed in accordance with COGCC 1003 Rules. Inspection required Operator to Comply with Rule 1003.b.

It was observed in this inspection that interim reclamation has not been conducted on the Location in accordance with 1003 Rules, and per corrective actions.

Original corrective action and date remains applicable.

Corrective Action

Comply with Rule 1003.b and conduct reclamation on areas not needed for production. Install BMPs to stabilize the seeded soil in accordance with Rule 1002.f, and continue to monitor and manage interim areas until Final Reclamation has passed. A CA date of 03/01/2016 is being provided as this is when Laramie took ownership of the Location.

Date 03/01/2016Overall Interim Reclamation Fail**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Inspection #696202120 observed stormwater and erosion control BMPs to protect, stabilize and prevent off-site sediment transport from the cut/fill slopes of the Location were missing or insufficient. Inspection required Operator to implement temporary control measures by 1/11/2021 until interim reclamation was conducted, at which point long-term controls were required in accordance with Rule 1002.f.

It was observed in this inspection that temporary perimeter controls (wattles) have been implemented; however, BMPs to protect and stabilize the cut and full slopes of the Location remain missing or insufficient/inadequate.

This corrective action has not been addressed and remains applicable.

Corrective Action: Comply with Rule 1002.f. and install BMPs in accordance with good engineering practices. Temporary controls will be required by 1/11/2021 until interim reclamation of the Location is conducted, at which point long-term controls will need to be implemented.

Date: 01/11/2021

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402729364	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5463805
696202857	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5463802