

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2021

Submitted Date:

06/25/2021

Document Number:

694500339**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 100 CHEVRON ROADCity: RANGELY State: CO Zip: 81648**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Patterson, Chris C		SPWU@chevron.com	CEMC
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480059	SPILL OR RELEASE	AC	06/01/2021		-	Purdy 2X1	EI

**General Comment:**

On 5/25/2021, COGCC staff, Kris Neidel inspected spill # 480059. The spill was reported as subsurface and occurred when an excavation clipped a line containing produced water and oil, the spill was reported as contained in the excavation. At the time of inspection the excavations were not open. Disturbed soil was observed in an area that had flowline markers indicating "Purdy 2x1". No fluid or hydrocarbon was observable at time of inspection. Corrective Action: Delineate the horizontal and vertical extent of impacted area and remediate impacts to Table 915-1 standards. Due to; location of this spill, near river, near public access a short timeline to delineation and remediation is highly encouraged.



**Environmental****Spill/Remediation:**Comment: [Spill was reported as spill # 480059](#)Corrective Action: **Delineate the horizontal and vertical extent of impacted area and remediate impacts to Table 915-1 standards. Due to; location of this spill, near river, near public access a short timeline to delineation and remediation is highly encouraged.**Date: 07/25/2021

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402730665	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5464927">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5464927</a>
694500340	photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5464915">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5464915</a>