

TEP  
KP 33-18  
Location # 417271



location



location

TEP  
KP 33-18  
Location # 417271



location



location

TEP  
KP 33-18  
Location # 417271



**Perimeter ditch is full of sediment and over running causing some riling and undermining**



**Perimeter ditch is full of sediment and over running causing some riling and undermining**

TEP  
KP 33-18  
Location # 417271



Jul 1, 2021 at 11:59:52 AM  
+39.526083, -107.595140 ±4.73r  
COGCC

**Perimeter ditch is full of sediment and over running causing some riling and undermining. Red line is downhill side of ditch.**



Jul 1, 2021 at 12:00:19 PM  
+39.526083, -107.595140 ±4.73r  
COGCC

**Perimeter ditch is full of sediment and over running causing some riling and undermining**

