

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402740413

Date Received:
07/07/2021

FIR RESOLUTION FORM

Overall Status: BOTH

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

2 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Labowskie, Steve	970-563-4000	steve.labowskie@state.co.us
Hahn, Travis	970-563-4000	maralextech@gmail.com thahn@maralexinc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903335
Inspection Date: 06/29/2021 FIR Submit Date: 07/01/2021 FIR Status:

Inspected Operator Information:

Company Name: MARALEX RESOURCES INC Company Number: 53255
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

LOCATION - Location ID: 334029

Location Name: CONLEY-N32N6W Number: 24NENW County: ARCHULETA
Qtrqtr: NENW Sec: 24 Twp: 32N Range: 6W Meridian: N
Latitude: 37.007190 Longitude: -107.453540

FACILITY - API Number: 05-007-00 Facility ID: 275602

Facility Name: CONLEY Number: 6
Qtrqtr: NENW Sec: 24 Twp: 32N Range: 6W Meridian: N
Latitude: 37.007190 Longitude: -107.453540

CORRECTIVE ACTIONS:

1 CA# 152374

Corrective Action: -Remove landowner equipment or obtain an approved variance. Corrective action was identified during Dec. 2020 inspection.

Date:

Response: FACTUAL REVIEW REQUEST

Basis for Review: Action requested was already completed prior to the inspection

Land owner has applied for an variance. Do we need to apply again?

Operator
Comment:

COGCC Decision: **Not Approved**

COGCC
Representative:

It is the operator's responsibility to control their location and apply for a variance. It is not the landowners responsibility. Per the new COGCC rules, there is a new variance process since the 1/15/2021 rule change; requiring a hearings application to the commission per Rules 502 and 510. Variances should no longer be submitted with a Form 4 Sundry.

COGCC
Supervisor:

It is the operator's responsibility to control their location and apply for a variance. It is not the landowners responsibility. Per the new COGCC rules, there is a new variance process since the 1/15/2021 rule change; requiring a hearings application to the commission per Rules 502 and 510. Variances should no longer be submitted with a Form 4 Sundry.

2 CA# 152375

Corrective Action: Control weeds

Date: _____

Response: CA COMPLETED

Date of Completion: 07/07/2021

Operator
Comment:

Weeds are worked on daily.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 CA# 152376

Corrective Action: -Remove and properly dispose of trash and debris. Corrective action was identified during Dec. 2020 inspection.

Date: _____

Response: CA COMPLETED

Date of Completion: 07/07/2021

Operator
Comment:

Trash has been removed and disposed of.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Land owner has requested a variance, please let us know if we should as well. All surface owner equipment is clear of production area.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Travis Hahn

Signed: _____

Title: Production Tech

Date: 7/7/2021 2:15:17 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
-----------------	-------------

402740413	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files