

TEP
Government 298-22-2
Location # 315689



location



location

TEP
Government 298-22-2
Location # 315689



Lack of battery signage



Lack of quantity on tank

TEP
Government 298-22-2
Location # 315689



Lack of stabilization/compaction



Sediment is migrating from location

TEP
Government 298-22-2
Location # 315689



Sediment is migrating from location



Arrows indicate failing BMP's/berm at entrance