

TEP
Federal 27-5
Location # 316109




Location/ lack of battery signage



location



TEP
Federal 27-5
Location # 316109



Location/ signage



Well head sign on ground

TEP
Federal 27-5
Location # 316109



Debris and possible leak



Debris

TEP
Federal 27-5
Location # 316109



Erosion through berm at entrance of location



Erosion through berm at entrance of location

TEP
Federal 27-5
Location # 316109



Erosion channel just off of location entrance



**Erosion channel just off of location entrance/
Sediment migration from location**



TEP
Federal 27-5
Location # 316109



Sediment migration from location



Lack of stabilization/compaction



TEP
Federal 27-5
Location # 316109



Lack of stabilization/compaction



Lack of stabilization/compaction

