

Inspection Photos

7/12/2021

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 452055

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 452055



Photo 1: Photo taken from the cut slopes on the east end of the Location. Photo shows control measures to protect and stabilize slopes of the Location remain missing or insufficient; soils predominantly exposed and loose.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 452055



Photo 2: Photo taken from the cut slopes on the east end of the Location. Photo shows control measures to protect and stabilize slopes of the Location remain missing or insufficient; soils predominantly exposed and loose.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 452055



Photo 3: Photo taken from the cut slopes on the east end of the Location. Photo shows control measures to protect and stabilize slopes of the Location remain missing or insufficient; soils predominantly exposed and loose. Erosion degradation evident.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 452055



Photo 4: Photo taken from the soil stockpile on the west end of the Location. Photo shows control measures to protect and stabilize slopes of the Location remain missing or insufficient; soils predominantly exposed and loose.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 452055



Photo 5: Photo taken from the south end of the Location. Previous inspection observed erosion degradation within area due to stormwater runoff from the Location. Inspection required Operator to implement BMPs to manage runoff. Photo shows erosion has been repaired, however, BMPs to manage runoff from the Location remain missing or insufficient.