

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402754953

Date Received:  
07/21/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 77330

Name of Operator: SG INTERESTS I LTD

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

• dnr\_cogccenforcement@state.co.us

• inspection@sginterests.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202716

Inspection Date: 05/21/2021

FIR Submit Date: 05/25/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: SG INTERESTS I LTD

Company Number: 77330

Address: 100 WAUGH DR SUITE 400

City: HOUSTON State: TX Zip: 77007

LOCATION - Location ID: 418697

Location Name: VOLK Number: 12-89-21 #1 County: \_\_\_\_\_

Qtrqtr: SENW Sec: 21 Twp: 12S Range: 89W Meridian: 6

Latitude: 39.002890 Longitude: -107.341720

FACILITY - API Number: 05-051-00 Facility ID: 418697

Facility Name: VOLK Number: 12-89-21 #1

Qtrqtr: SENW Sec: 21 Twp: 12S Range: 89W Meridian: 6

Latitude: 39.002890 Longitude: -107.341720

CORRECTIVE ACTIONS:

1 CA# 151367

Corrective Action: Comply with Rule 1004.e

Date: 06/08/2021

Response: CA COMPLETED

Date of Completion: 07/06/2021

Operator Comment: This corrective action was completed and addressed in FIR Resolution Form doc#402743893

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

2 CA# 151368

Corrective Action: Install or repair required BMPs in accordance with good engineering practices per Rule 1002.f.(2)C. Conduct revegetation/reseeding activities on the slopes and install erosion controls to stabilize the seeded soil.

Date: 06/11/2020

Response: CA COMPLETED

Date of Completion: 07/13/2021

Operator Comment: Stormwater diversion ditch along the perimeter of the location, including armoring and outlets, has been maintained and in proper functioning condition. Silt fence on the west end of the location has been maintained and in proper functioning condition. Additional revegetation activities have been conducted per SG's plan for this location, which has been previously communicated with COGCC. Hydromulch, soil amendment and seed has been spread on disturbed areas to stabilize and protect slopes. Additional seeding has occurred. Fencing has been placed around revegetated areas to assist with vegetation growth. Seeded areas will be watered as needed depending on weather. See attached photos.

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Eric Sanford

Signed:

Title: Land

Date: 7/21/2021 2:15:08 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402754982	Volk Fencing and revegetation_1
402754986	Volk Fencing and revegetation_2
402754988	Volk Silt Fencing Maintained
402755244	Volk Hydromulch, Soil Amendment, Seeding on Slopes_1
402755255	Volk Hydromulch, Soil Amendment, Seeding on Slopes_2
402755257	Volk Hydromulch, Soil Amendment, Seeding on Slopes_3
402755261	Volk Seeding_Revegetation_Straw Application
402755683	Volk Diversion Ditch_1
402755684	Volk Diversion Ditch_2
402755707	Volk Rock Dam and Outlet Protection_1
402755709	Volk Rock Dam and Outlet Protection_2
402755716	Volk Rock Dam and Outlet Protection_3

Total Attach: 12 Files