

Inspection Photos
E. Stieber Consolidation
Spill ID 480275 (AC)



**Photo 1 – Spill excavation. Impacts remain in situ.
Free product visible on groundwater.**



**Photo 2 – Spill excavation. Impacts remain in situ.
Free product visible on groundwater.**

Inspection Photos
E. Stieber Consolidation
Spill ID 480275 (AC)



**Photo 3 – Spill excavation. Impacts remain in situ.
Free product visible on groundwater.**



**Photo 4 – Spill excavation being backfilled. Impacts
remain visible in-situ and free product visible on
groundwater.**