

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2021

Submitted Date:

07/21/2021

Document Number:

689806021**FIELD INSPECTION FORM**Loc ID 316764 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 6720Name of Operator: ROBERT L BAYLESS PRODUCER LLCAddress: 621 17TH ST STE 2300City: DENVER State: CO Zip: 80293**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Helen		notices@rlbayless.com	All inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	
thomas, john	505-326-2659	jthomas@rlbayless.com	

General Comment:

Inspector on location in response to venting complaint. Complaint document number 200449782. FLIR inspection performed in response to complaint. Venting observed at vent tank, vertical separator, and wellhead.

Optical Gas Imaging SurveySurvey Type: ComplaintCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 40.395400 Long: -107.221837Wind: Calm Speed: (mph) Direction From: S Weather: Clear Temperature: (F)Assisting Staff: Emily Waldron Camera #: 3☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
11:00	AM	11:10	AM

Equipment
Wellhead(s)
Other
Separation Equipment

Comment: FLIR video documented venting at vent tank, wellhead, and vertical separator. Inspector spoke with John Thomas of Bayless on 7/21 and was informed that pumper would be sent out to address leaks at wellhead and separator and that operator was in communication with CDPHE regarding how to manage casing gas on location.

Corrective Action: Immediately cease venting/flaring. Submit Form 4 for review and approval to vent or flare.

Date: 07/22/2021**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402755146	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5485035
689806022	FLIR - wellhead venting	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5485032
689806023	FLIR - separator venting	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5485033
689806024	FLIR - vent tank venting	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5485034