

FORM

6

Rev  
11/20

## State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE

ET

OE

ES

Replug By Other Operator

Document Number:

402762052

Date Received:

07/28/2021

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10110

Contact Name: Kapri McMillan

Name of Operator: GREAT WESTERN OPERATING COMPANY LLC

Phone: (970) 364-2826

Address: 1001 17TH STREET #2000

Fax:

City: DENVER State: CO Zip: 80202

Email: kmcmillan@gwp.com

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

Type of Well Abandonment Report:



Notice of Intent to Abandon



Subsequent Report of Abandonment

API Number 05-001-06988-00

Well Name: GUTSHALL

Well Number: 1

Location: QtrQtr: NENW

Section: 31

Township: 1S

Range: 66W

Meridian: 6

County: ADAMS

Federal, Indian or State Lease Number:

Field Name: WATTENBERG

Field Number: 90750

## Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.926108

Longitude: -104.821916

GPS Data: GPS Quality Value: 1.5

Type of GPS Quality Value: PDOP

Date of Measurement: 02/03/2021

Reason for Abandonment:


☐ Other

Casing to be pulled:



Estimated Depth:

Fish in Hole:



If yes, explain details below

Wellbore has Uncemented Casing leaks:



If yes, explain details below

Details:

## Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
D SAND	8194	8198	06/01/1976	SAND PLUG/CEMENT	8128
J SAND	8255	8278	06/01/1976	SAND PLUG/CEMENT	8128

Total: 2 zone(s)

## Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/2	8+5/8		24	0	240	200	240	0	
1ST	7+7/8	4+1/2		10.5	0	8325	300	8325	7294	CALC

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set	200	sks cmt from	5204	ft. to	4848	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input type="checkbox"/>
Set	50	sks cmt from	4802	ft. to	4632	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input type="checkbox"/>
Set	200	sks cmt from	2500	ft. to	2015	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input type="checkbox"/>
Set	40	sks cmt from	2015	ft. to	1840	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input type="checkbox"/>
Set	122	sks cmt from	1829	ft. to	1442	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input type="checkbox"/>

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 395 sacks half in. half out surface casing from 651 ft. to 0 ft. Plug Tagged: ☐

Set 25 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing

Surface Plug Setting Date: 06/06/2021 Cut and Cap Date: 06/29/2021 Number of Days from Setting Surface Plug to Capping or Sealing the Well: 23

\*Wireline Contractor: \_\_\_\_\_

\*Cementing Contractor: Swabbco

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

set 200 sx from 1426' to 677' open hole

After pumping the plug from 2500' to ETOC 1820', we WOC 4 hours before tagging the plug and pumping the next plug. The next plug from 1581' to ETOC 901' tagged significantly higher at 498' and there was 40 psi on the casing so we decided to mill out the cement to a depth of 2015'. We then pumped smaller plugs to verify migration was stopped each time, we did not see any migration so we pumped to surface.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Renee Kendrick

Title: SR Regulatory Analyst Date: 7/28/2021 Email: rkendrick@gwp.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Jacobson, Eric Date: 7/28/2021

CONDITIONS OF APPROVAL, IF ANY:

### Condition of Approval

**COA Type****Description**

0 COA	

### Attachment List

**Att Doc Num****Name**

402762052	FORM 6 SUBSEQUENT SUBMITTED
402762103	WELLBORE DIAGRAM
402762104	CEMENT JOB SUMMARY

Total Attach: 3 Files

### General Comments

**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)