

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402769446

Date Received:

08/03/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10691

Name of Operator: PHOENIX RESOURCES LLC

Address: 5566 S SYCAMORE STREET

City: LITTLETON State: CO Zip: 80120

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Taylor Heffner

303-219-3362

theffner@phxresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689806018

Inspection Date: 07/15/2021

FIR Submit Date: 07/16/2021

FIR Status: _____

Inspected Operator Information:

Company Name: PHOENIX RESOURCES LLC

Company Number: 10691

Address: 5566 S SYCAMORE STREET

City: LITTLETON State: CO Zip: 80120

LOCATION - Location ID: 316742

Location Name: MARY HITE FEE-65N87W Number: 31SWNW County: ROUTT

Qtrqr: SWN Sec: 31 Twp: 5N Range: 87W Meridian: 6
W

Latitude: 40.350533 Longitude: -107.197167

FACILITY - API Number: 05-107- -00 Facility ID: 232600

Facility Name: MARY HITE FEE Number: 1

Qtrqr: SWN Sec: 31 Twp: 5N Range: 87W Meridian: 6
W

Latitude: 40.350533 Longitude: -107.197167

CORRECTIVE ACTIONS:

1 CA# 153866

Corrective Action: Immediately cease venting/flaring. Submit Form 4 for review and approval to vent or flare.
Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 07/17/2021

Response: CA COMPLETED

Date of Completion: 07/15/2021

The well is no longer venting through the thief hatch and vent pipe off the production tank since being shut in on

Operator Comment: 7/15/2021. This was done after Phoenix Resources received an email from the CDPHE that a FLIR camera video had been taken of our location which showed venting from the production tank. Since shutting in the well, we have ordered an Enardo stack valve and new thief hatch to address the venting. Additionally, we have submitted a Form 4 - Request to Vent, since emissions from our thief hatch and vent pipe are due to breathing losses. There is no saleable gas produced from the Mary Hite Fee well, and this location is APEN exempt as it is and <2 tpy using State default emissions factor for crude oil in Routt County.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Upon approval of our Form 4 - Request to Vent and installation of Enardo stack valve and new thief hatch, Phoenix Resources plans to put the well back on production.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Taylor Heffner

Signed: _____

Title: Partner

Date: 8/3/2021 3:32:29 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files