

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/03/2021

Submitted Date:

08/03/2021

Document Number:

690201906

**FIELD INSPECTION FORM**Loc ID 309122 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD State: CO Zip: 8111-

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mack, Ronald		rmack@ogrisop.com	
		timothy.thomsen@state.co.us	
Fitzgerald, Edie		efitzgerald@ogrisop.com	
ATWATER BONNIE		batwater@ogrisop.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288299	WELL	PR	05/09/2008	GW	071-09111	GOLDEN EAGLE 29-16	RI

**General Comment:**

This is a location and stormwater management inspection.  
See attached photos and additional details within this report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
Produced Water	WELLHEAD			
Comment:	There is a dripping water leak at the wellhead that needs to be repaired.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: <u>08/05/2021</u>

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is erosion along the access road traveling to the location. The cattleguard is not maintained and is filled in with sediment. There is erosion along the side of the road which needs BMP's to prevent further erosion.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 09/01/2021

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	292686	2059199	
	292686	2059199	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690201907	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5497436">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5497436</a>