

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /3NWSW

Location ID: 334788



Photo #4694 from entrance to location.



Photo #4695 from entrance to location.



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /3NWSW

Location ID: 334788



Photo #4697 No battery sign located at the tank battery.



Photo #4696 Location lacks stabilization.



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /3NWSW

Location ID: 334788



Photo #4698 Location lacks stabilization.




Photo #4699 Insufficient tracking BMP.