

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402751809

Date Received:
07/19/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Christina Pierce

970-263-3626

cpierce@Laramie-Energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202924

Inspection Date: 07/12/2021

FIR Submit Date: 07/13/2021

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1401 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 452807

Location Name: CC Number: 0697-03-07 County: _____
Pad

Qtrqtr: Lot 11 Sec: 3 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.558439 Longitude: -108.205081

FACILITY - API Number: 05-045- -00 Facility ID: 452807

Facility Name: CC Number: 0697-03-07
Pad

Qtrqtr: Lot 11 Sec: 3 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.558439 Longitude: -108.205081

CORRECTIVE ACTIONS:

1 ☒ CA# 152713

Corrective Action: Comly with Rule 1003.f

Date: 07/27/2021

Response: CA COMPLETED

Date of Completion: 07/16/2021

Operator
Comment: issue addressed see attached report

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3  CA# 152715

Corrective Action: Comply with Rule 1002.f.(2) and install BMPs in accordance with good engineering practices. Temporary controls will be required by 1/10/2021 until interim reclamation of the Location is conducted, at which point long-term controls will need to be implemented.

Date: 01/10/2021

Response: CA COMPLETED

Date of Completion: 07/16/2021

Operator
Comment: issue addressed see attached report

COGCC Decision: **Not Approved**

COGCC
Representative:

Inspection #696202924 documented that BMPs to protect and stabilize and the cut and fill slopes of the Location, and access road are missing or insufficient.

Documents attached shows Operator has placed a wattle along the toe of the slopes of the access road; no other control measures documented within the resolution; BMP alone is an inadequate control measure to address stabilization concerns on the slopes.

Additionally, Operator has not provided documentation showing adequate BMPs to protect and stabilize the cut and fill slopes of the Location have been implemented per good engineering practices, per the corrective action.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Christina Pierce

Signed:

Title: Engineering Tech

Date: 7/19/2021 12:53:47 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402751809	FIR RESOLUTION SUBMITTED
-----------	--------------------------

402751813	corrective action
-----------	-------------------

Total Attach: 2 Files