

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/29/2021

Submitted Date:

07/30/2021

Document Number:

693903489**FIELD INSPECTION FORM**Loc ID 312051 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: THREE ALLEN CENTER, 333 CLAY ST SUITE 3900City: HOUSTON State: TX Zip: 77002**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Arthur, Denise		denise.arthur@state.co.us	
, General		sjninspections@ikavenergy.com	All Inspections
Hughes, Jim		jimo.hughes@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263927	WELL	PR	02/15/2021	GW	067-08731	BARNES A 2	RI

General Comment:

On 7/29/2021 Catherine Roy conducted a reclamation and stormwater inspection. It is apparent that recent precipitation has resulted in flood/stormwater transport across the well pad. During this inspection the following compliance issues were observed:

-Remove and properly manage gravel, rock, and material displaced and discharged downslope of the well pad. Remove and properly dispose of debris deposited on well pad and around facilities. Submit (as an attachment to a Form 4) and implement a plan to properly divert and protect the location from degradation during significant stormwater events on the well pad using good engineering practices. All inlets and outlets need to be properly designed and constructed to ensure stabilization. Corrective action date is the day of the inspection (7/29/2021) as it is required that the corrective action be addressed immediately.

-Per Rule 421.b. for wells within the 100 year floodplane submit as an attachment to a Form 4, Operator's Flood Shut-In Plan by 8/2/2021.

This is a shared location between Simcoe and Logos. It is the responsibility of both operator's to ensure compliance with COGCC rules.

Per communication with Steve Labowskie on 7/29/2021, Operator was contacted and notified of issues observed at this time.

See below, and attached photos for additional detail.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type:	#		corrective date
Comment:			
Corrective Action:	-Per Rule 421.b. for wells within the 100 year floodplane submit as an attachment to a Form 4, Operator's Flood Shut-In Plan by 8/2/2021.		Date: <u>08/02/2021</u>

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Large volumes of well pad material is washed downslope from the well pad and likely into the Florida River. Debris is deposited around well facilities.

Corrective Action: -Remove and properly manage gravel, rock, and material displaced and discharged downslope of the well pad. Remove and properly dispose of debris deposited on well pad and around facilities. Submit (as an attachment to a Form 4) and implement a plan to properly divert and protect the location from degradation during significant stormwater events on the well pad using good engineering practices. All inlets and outlets need to be properly designed and constructed to ensure stabilization. Corrective action date is the day of the inspection (7/29/2021) as it is required that the corrective action be addressed immediately.

Date: 07/29/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402766563	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5494727
693903490	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5494724