

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/03/2021

Submitted Date:

08/03/2021

Document Number:

693505371

FIELD INSPECTION FORM

Loc ID 318381 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241194	WELL	SI	04/01/2021	GW	123-08982	UPRR 43 PAN AM G 12	SI

General Comment:

Location			
Lease Road:			
Type	Access		
comment:	Weeds on access road have not been maintained.		
Corrective Action	Comply with rule 606	Date:	09/03/2021
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Mechanical issue: Electric motor not connected to power supply. meter appears to have been removed.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	09/03/2021
Type	UNUSED EQUIPMENT		
Comment:	PU and associated equipment due to not power on site.		
Corrective Action:	Comply with rule 606.	Date:	09/03/2021
Type	WEEDS		
Comment:	Weeds not maintained on well site.		
Corrective Action:	Comply with rule 606	Date:	09/03/2021
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Hog panel.		
Corrective Action:		Date:	
Equipment:			
Type: Prime Mover	# 1		corrective date
Comment:	Electric motor		
Corrective Action:		Date:	

Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Unused electric panel		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241194 Type: WELL API Number: 123-08982 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: At time of inspection well is SI in compliance with the COGCC Director's order under rule 901.a. of the Rules and Regulations of the Colorado Oil and Gas Conservation Commission, 2 CCR 404-1 ("Rule" or "Rules"). As part of this order the operator KPK (Operator No. 46290) was ordered to immediately suspend all production operations at these assigned location.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 07/23/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday August 3, 2021 at approximately 11:42AM, I, Inspector Randy Silver, conducted an on-site inspection. Location: UPRR 43 Pan AM G#12 Operator: KP Kauffman API#: 123-08982 County: Weld While there, I observed a well site. During this inspection the following possible compliance issues were observed: Unused equipment: Rule 606 corrective action date of 9-3-21 See Photo's 5,6 Weeds: Rule 606 Corrective action date of 9-3-21 See Photos 1,2,4 Mechanical issue: Rule 608 e Corrective action date of 9-3-21 See photos 5,6 Weather conditions: Dry A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	08/03/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402769259	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5496847
693505372	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5496817