

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/03/2021

Submitted Date:

08/03/2021

Document Number:

690201906

FIELD INSPECTION FORMLoc ID 309122 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD State: CO Zip: 8111-

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fitzgerald, Edie		efitzgerald@ogrisop.com	
Mack, Ronald		rmack@ogrisop.com	
		timothy.thomsen@state.co.us	
ATWATER BONNIE		batwater@ogrisop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288299	WELL	PR	05/09/2008	GW	071-09111	GOLDEN EAGLE 29-16	RI

General Comment:

This is a location and stormwater management inspection.
See attached photos and additional details within this report.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐**Spills:**

Type	Area	Volume		
Produced Water	WELLHEAD			
Comment:	There is a dripping water leak at the wellhead that needs to be repaired.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 08/05/2021

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is erosion along the access road traveling to the location. The cattleguard is not maintained and is filled in with sediment. There is erosion along the side of the road which needs BMP's to prevent further erosion.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 09/01/2021

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402769911	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5497448
690201907	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5497436