

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/03/2021

Submitted Date:

08/03/2021

Document Number:

690201908

FIELD INSPECTION FORM

Loc ID 309141 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10672
 Name of Operator: TIMBER CREEK OPERATING LLC
 Address: 6295 GREENWOOD PLAZA BLVD #100
 City: GREENWOOD State: CO Zip: 8111-

Findings:

- 4 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fitzgerald, Edie		efitzgerald@ogrisop.com	
Mack, Ronald		rmack@ogrisop.com	
ATWATER BONNIE		batwater@ogrisop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288584	WELL	PR	12/27/2006	GW	071-09140	GOLDEN EAGLE 32-4	RI

General Comment:

[This is a location and stormwater management inspection.](#)
[See attached photos and additional details within this report.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	There were noxious along areas of the road and at the edge of the well pad. It appeared weed control had been performed but follow up control should be performed.		
Corrective Action:	Comply with Rule 1003.f.		Date: <u>09/15/2021</u>

Overall Good:

Spills:

Type	Area	Volume		
Produced Water	WELLHEAD			
Comment:	There is a dripping water leak at the wellhead that needs to be repaired.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: <u>08/05/2021</u>

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is erosion along the side of the road which needs BMP's to prevent further erosion.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 09/01/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402769915	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5497452
690201909	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5497437