

State of Colorado
Oil and Gas Conservation Commission
DEPARTMENT OF NATURAL RESOURCES

FOR OGCC USE ONLY

RECEIVED

SEP 25 97

COGCC

WELL ABANDONMENT REPORT

This form is to be submitted as an intent whenever a plugging is planned on a borehole. The approved intent shall be valid for one year after the approval date; after that period a new intent will be required. After the plugging is complete, this form shall again be submitted as a subsequent report of the work as actually completed.

OGCC Operator Number: 59100	Contact Name & Phone
Name of Operator: Rex Monahan	James Rowland
Address: P.O. Box 1231	No: (970) 522-0774
City: Sterling State: CO Zip: 80751	Fax: (970) 522-8744
API Number: 05- 075063720	
Well Name: Mt. Hope - Green Number: 20	
Location (QtrQtr, Sec, Twp, Rng, Meridian): SW SW Sec. 19-T9N-R53W	
County: Logan Federal, Indian or State lease number:	
Field Name: Mt. Hope Field Number: 56150	

ET	OE	PR	ES
24 hour notice required, contact			
Complete the Attachment Checklist			
Wellbore Diagram	Opér	OGCC	
Cement Job Summary	X		
Wireline Job Summary			

X

Notice of Intent to Abandon

Subsequent Report of Abandonment

Background for Intent Only

Reason for abandonment:	<input type="checkbox"/> Dry	<input checked="" type="checkbox"/> Production Sub-economic	<input type="checkbox"/> Mechanical Problems	<input type="checkbox"/> Other
Casing to be pulled:	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	Top of casing cement: 3965' KB	
Fish in hole:	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes	If yes, explain details below:	
Wellbore has uncemented casing leaks:	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes	If yes, explain details below:	
Details:				

Current and Previously Abandoned Zones

Formation	Perforations	Date	Method of Isolation (None, Squeezed, BP, Cement, etc.)	Plug Depth
D Sandstone	4864'-4885' KB			

Casing History

Casing String	Size	Cement Top	Stage Cement Top
Surface	8-5/8" O.D., 32#/ft.	Surface	
Production	4-1/2" O.D., 9.5#/ft.	3965' KB (temp. svy.)	

Plugging Procedure for Intent and Subsequent Report

1. CIBP #1 Depth	CIBP #2 Depth	CIBP #3 Depth	NOTE: Two (2) sacks cement required on all CIBPs
2. Set 30 sks cmt from 4534 ft. to 4885 ft. in	<input checked="" type="checkbox"/> Casing	<input type="checkbox"/> Open Hole	<input type="checkbox"/> Annulus
3. Set 40 sks cmt from 800 ft. to 700 ft. in	<input type="checkbox"/> Casing	<input type="checkbox"/> Open Hole	<input type="checkbox"/> Annulus
4. Set sks cmt from ft. to ft. in	<input type="checkbox"/> Casing	<input type="checkbox"/> Open Hole	<input type="checkbox"/> Annulus
5. Set sks cmt from ft. to ft. in	<input type="checkbox"/> Casing	<input type="checkbox"/> Open Hole	<input type="checkbox"/> Annulus
6. Set sks cmt from ft. to ft. in	<input type="checkbox"/> Casing	<input type="checkbox"/> Open Hole	<input type="checkbox"/> Annulus
7. Perforate and squeeze @ ft. with SKS	Leave at least 100 ft. in casing		
8. Perforate and squeeze @ ft. with SKS	Leave at least 100 ft. in casing		
9. Perforate and squeeze @ ft. with SKS	Leave at least 100 ft. in casing		
10. Set 30 40 SKS 1/2 in 1/2 out surface casing from 300 ft. to 400 ft.			
11. Set 15 SKS @ surface			
Cut 4 feet below ground level, weld on plate			
Set SKS in rate hole	Dry-Hole Marker	<input type="checkbox"/> No	<input type="checkbox"/> Yes
Set SKS in mouse hole			

Additional Plugging Information for Subsequent Report Only

Casing recovered: ft. of in. casing	Plugging date:
*Wireline contractor:	
*Cementing contractor:	
Type of cement and additives used:	
*Attach job summaries.	

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name James Rowland

Signed James Rowland Title: Engineer Date: Sept. 24, 1997

OGCC Approved: D K DILLON Title: SR. PETROLEUM ENGINEER Date: OCT 08 1997

CONDITIONS OF APPROVAL, IF ANY: SET AN ADDITIONAL 40 SACK PLUG AT 800'. SET 40 SACK PLUG AT SURFACE CASING SHOE.

insufficient copies of this form were submitted.