

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /32SWNE

Location ID: 335241



Photo #4760 from entrance to location.



Photo #4761 Tank battery sign weathered and not legible.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /32SWNE

Location ID: 335241



Photo #4762 Separators missing required information.



Photo #4763 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /32SWNE

Location ID: 335241



Photo #4764 Location lacks stabilization.



Photo #4764 Insufficient tracking control at entrance to location.