

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402780079

Date Received:

08/13/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Atwater, Bonnie

batwater@ogrisop.com

Fitzgerald, Edie

efitzgerald@ogrisop.com

O'Shields, Charlie

940-682-5030

coshields@ogrisop.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690201931

Inspection Date: 08/06/2021

FIR Submit Date: 08/09/2021

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 333928

Location Name: HILL RANCH-634S67W Number: 32SENW County: LAS ANIMAS

Qtrqtr: SENW Sec: 32 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.042610 Longitude: -104.911630

FACILITY - API Number: 05-071- -00 Facility ID: 275202

Facility Name: HILL RANCH Number: 32-06CH

Qtrqtr: SENW Sec: 32 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.042610 Longitude: -104.911630

CORRECTIVE ACTIONS:

1 CA# 154630

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 08/11/2021

Response: CA COMPLETED

Date of Completion: 08/11/2021

Operator Comment: THERE WERE NO PIPELINE ISSUES, SOMEONE UNCOVERED THE VALVE CAN TO SEE WHAT WAS INSIDE AND FAILED TO REPLACE THE LID AS IT WAS TOO HEAVY. THE WATER IN THE VALVE BOX WAS RAIN WATER ONLY.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 154631

Corrective Action: Cover and protect the the valve box to prevent entry.

Date: 08/11/2021

Response: CA COMPLETED

Date of Completion: 08/11/2021

Operator Comment: THE ORANGE FLAGGER TAPE WAS REMOVED. THIS WAS USED TO MARK THE END OF THE LEASE RUN FOR NEW EMPLOYEE'S/CONTRACTOR'S. THERE WERE NO PIPELINE ISSUES, SOMEONE UNCOVERED THE VALVE CAN TO SEE WHAT WAS INSIDE AND FAILED TO REPLACE THE LID AS IT WAS TOO HEAVY. THE VALVE CAN COVER WAS PLACED BACK ON TOP OF THE VALVE CAN.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. SEE ATTACHED PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: Sr. Environmental Tech.

Date: 8/13/2021 1:36:54 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402780116	PHOTO LOG
-----------	-----------

Total Attach: 1 Files