

TEP
GV 15-36
Location # 323840



Location/lack of separator bath signage



Location/lack of separator bath signage

TEP
GV 15-36
Location # 323840



location



location

TEP
GV 15-36
Location # 323840



Lack of bull plug/cap



Lack of bull plug/cap

TEP
GV 15-36
Location # 323840



Wildlife netting open

