

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/16/2021

Submitted Date:

08/18/2021

Document Number:

690201972

**FIELD INSPECTION FORM**

Loc ID 308156 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1875 LAWRENCE ST STE 1150  
City: DENVER State: CO Zip: 80202

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263051	WELL	PR	12/10/2002	GW	071-07604	COACH 21-34	RI

**General Comment:**

[This is a stormwater management inspection.](#)  
[See attached photos and additional details within this report.](#)

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: The stream crossing which was washed out in the spring flood event has been rebuilt. There are multiple culverts of various sizes installed which does not appear to be an engineered installation. Further along the access road are multiple culverts filled in with sediment that need maintenance. Areas of erosion along the access road need to be repaired. The stream crossing needs to be installed per good engineer practice demonstrated by a stamped engineer design plan submitted by form 4.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 09/30/2021

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690201973	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5509318">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5509318</a>