

TEP
RMV 202-20
Location # 335273



location



location

TEP
RMV 202-20
Location # 335273



location



location/separator baths missing labels

TEP
RMV 202-20
Location # 335273



Load out lines missing bull plugs/caps



Load out lines missing bull plugs/caps



TEP
RMV 202-20
Location # 335273



Lack of stabilization/compaction



Lack of stabilization/compaction

