

TEP
RMV 25-20
Location # 335236



Aug 18, 2021 at 10:57:33 AM
+39.510979,-107.909336 ±4.71m
COGCC

location



Aug 18, 2021 at 10:57:37 AM
+39.510979,-107.909336 ±4.71m
COGCC

location

TEP
RMV 25-20
Location # 335236



location



Separator bath missing labeling

TEP
RMV 25-20
Location # 335236



Load out line missing bull plug/cap



Subsidence still occurring/debris

