

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

Document Number:
 402736143
 Date Received:

OGCC Operator Number: 96155 Contact Name: Andrew Fish
 Name of Operator: WHITING OIL & GAS CORPORATION Phone: (303) 357-4021
 Address: 1700 LINCOLN STREET SUITE 4700 Fax: _____
 City: DENVER State: CO Zip: 80290 Email: andrew.fish@whiting.com

For "Intent" 24 hour notice required, Name: Kellerby, Shaun Tel: (970) 285-7235
COGCC contact: Email: shaun.kellerby@state.co.us

Type of Well Abandonment Report: Notice of Intent to Abandon Subsequent Report of Abandonment

API Number 05-103-05041-00
 Well Name: SULPHUR FALLS GOVT Well Number: 1-A
 Location: QtrQtr: NWNE Section: 26 Township: 3S Range: 99W Meridian: 6
 County: RIO BLANCO Federal, Indian or State Lease Number: C-01398
 Field Name: SULPHUR CREEK Field Number: 80090

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.764052 Longitude: -108.468370
 GPS Data: GPS Quality Value: _____ Type of GPS Quality Value: _____ Date of Measurement: _____

Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other Re-plug by other operator. AL had casing set.

Casing to be pulled: Yes No Estimated Depth: 8850
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth

Total: 0 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	10+3/4	H-40	32.75	0	266	138	266	0	VISU
1ST	8+3/4	7	J-55	23	0	6120	975	6070	5000	CALC
1ST LINER	6+1/4	5	0	15	6065	8850	235	8850	6070	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 5 sks cmt from 760 ft. to 805 ft. Plug Type: STUB PLUG Plug Tagged:
Set 5 sks cmt from 245 ft. to 316 ft. Plug Type: STUB PLUG Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 799 ft. with 40 sacks. Leave at least 100 ft. in casing 770 CICR Depth
Perforate and squeeze at 315 ft. with 40 sacks. Leave at least 100 ft. in casing 275 CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from 245 ft. to 316 ft. Plug Tagged:

Set 20 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Number of Days from Setting Surface Plug to Capping or Sealing the Well: _____
Surface Plug Setting Date: _____ Cut and Cap Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:

Cement Plug: Set 20 sacks of cement from 100.0'ftKB to surface.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Pauleen Tobin

Title: Regulatory Compliance Date: _____ Email: pollyt@whiting.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: _____

COA Type	Description

Attachment List

<u>Att Doc Num</u>	<u>Name</u>
402787520	PROPOSED PLUGGING PROCEDURE
402787521	WELLBORE DIAGRAM
402787522	OTHER

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)