

FORM

21

Rev
11/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402787503

Date Received:

08/22/2021

MECHANICAL INTEGRITY TEST

1. Duration of the pressure test must be a minimum of 15 minutes.
2. An original pressure chart must accompany this report if this test was not witnessed by an OGCC representative.
3. For production wells, test pressures must be at a minimum of 300 psig.
4. New injection wells must be tested to maximum requested injection pressure.
5. For injection wells, test pressures must be at least 300 psig or average injection pressure, whichever is greater.
6. A minimum 300 psi differential pressure must be maintained between the tubing and tubing/casing annulus pressure.
7. Do not use this form if submitting under provisions of Rule 326.a(1)B. or C.
8. Written OGCC notification must be provided 10 days prior to the test via Form 42, Field Operations Notice
9. Packers or bridge plugs, etc., must be set within 100 feet of the perforated interval to be considered a valid test.

Complete the Attachment

Checklist

OP OGCC

OGCC Operator Number: 74165	Contact Name: Edward Ingve	Pressure Chart	
Name of Operator: RENEGADE OIL & GAS COMPANY LLC	Phone: (303) 829-2354	Cement Bond Log	
Address: 6155 S MAIN STREET #225		Tracer Survey	
City: AURORA State: CO Zip: 80016 Email: ed@renegadeoilandgas.com		Temperature Survey	
API Number: 05-039-06477	OGCC Facility ID Number: 209572	Inspection Number	
Well/Facility Name: NORDMAN ESTATE	Well/Facility Number: 10-7		
Location QtrQtr: SWNE Section: 10 Township: 6S Range: 64W Meridian: 6			

☒ SHUT-IN PRODUCTION WELL☐ INJECTION WELL

Last MIT Date: _____

Test Type:

☒ Test to Maintain SI/TA status☐ 5-Year UIC☐ Reset Packer☐ Verification of Repairs☐ Annual UIC TEST

☐ Describe Repairs or Other Well Activities: Retrievable BP was run to above perforations and the casing was loaded with water so that a CBL could be run. Renegade took advantage of this well preparation to perform a MIT. The casing failed the MIT test. On 8/18/2021 a packer was run to test the RBP making sure it was not the source of the pressure fall off. A squeeze job will now be scheduled.

Wellbore Data at Time of Test

Injection Producing Zone(s)	Perforated Interval	Open Hole Interval
DSND	8283-8305	

Tubing Casing/Annulus Test

Tubing Size:	Tubing Depth:	Top Packer Depth:	Multiple Packers?
			<input type="checkbox"/>

Casing Test

Use when perforations or open hole is isolated by bridge plug or cement plug; use if cased-hole only with plug back total depth.

Bridge Plug or Cement Plug Depth

8245

Test Data (Use -1 for a vacuum)

Test Date	Well Status During Test	Casing Pressure Before Test	Initial Tubing Pressure	Final Tubing Pressure
08-18-2021	SHUT-IN	0		
Casing Pressure Start Test	Casing Pressure - 5 Min.	Casing Pressure - 10 Min.	Casing Pressure Final Test	Pressure Loss or Gain
450	350	290	255	-195

Test Witnessed by State Representative? ☒

OGCC Field Representative

Sherman, Susan

OPERATOR COMMENTS:

Failed 08/23/2021 Well failed a MIT performed after a CBL was acquired as a COA for a new GMT offsetting horizontal well drilled. Well be repaired and retested.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: Edward Ingve

Title: Manager/Owner

Email: ed@renegadeoilandgas.com

Date: 8/22/2021

Based on the information provided herein, this Notice (Form 21) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: 8/22/2021

CONDITIONS OF APPROVAL, IF ANY:

Attachment List

Att Doc Num

Name

402787503

FORM 21 SUBMITTED

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

Agency

Well failed MIT and needs to repaired or plugged by 2/18/2022.

08/23/2021

Total: 1 comment(s)

FAILED